

# Barrett GCL (Grasper Control Language)

Friday, September 08, 2006

## {MOTORS}COMMAND{ PARAMETER}{ VALUE}

### Examples:

```
=> HI          "Initialize all four motors"  
=> 12C         "Close fingers 1 and 2"  
=> 4FSET DP 1300 "Set the Default Position of motor 4 to 1300"  
=> PGET TEMP   "Get the Temperature of the hand"  
=> SFGET MCV   "Get the Max Close Velocity of the Spread motor"  
=> GSM 2000     "Move the Grasp and Spread to position 2000"
```

### Motor Selectors:

```
{ "1",      "Finger/motor 1"},  
{ "2",      "Finger/motor 2"},  
{ "3",      "Finger/motor 3"},  
{ "4",      "Spread/motor 4"},  
{ "S",      "Spread/motor 4"},  
{ "G",      "Grasp (fingers 1, 2, & 3)"},
```

### GCL commands:

```
{ "O",      "Open"},  
{ "C",      "Close"},  
{ "TO",      "Torque Open"},  
{ "TC",      "Torque Close"},  
{ "IO",      "Incremental open"},  
{ "IC",      "Incremental close"},  
{ "M",      "Move to position"},  
{ "T",      "Terminate motor power"},  
{ "HOME",    "Go to home position"},  
{ "HI",      "Initialize and go to home"},  
{ "RESET",   "Reset hand software"},  
{ "VERS",    "Print hand software information"},  
{ "ERR",     "Print meaning of error number"},  
{ "?<cmd>", "Print help for a command"},  
{ "?",       "List commands"},  
{ "A?",     "List all commands"},  
{ "LOOP",   "Start loop control"},
```

### Finger parameter commands:

```
{ "FSET",   "Set finger parameters"},  
{ "FGET",   "Get finger parameters"},  
{ "FLLOAD", "Load finger parameters"},  
{ "FSAVE",  "Save finger parameters"},  
{ "FDEF",   "Set finger parameters to default"},  
{ "FLIST",  "List finger parameters"},  
{ "FLISTV", "List finger parameter values"},  
{ "FLISTA", "List all finger parameters"},  
{ "FLISTAV", "List all finger parameter values"},
```

### Hand parameter commands:

```
{ "PSET",   "Set global parameters"},  
{ "PGET",   "Get global parameters"},  
{ "PLLOAD", "Load global parameters"},  
{ "PSAVE",  "Save global parameters"},  
{ "PDEF",   "Set global parameters to default"},  
{ "PLIST",  "List global parameters"},  
{ "PLISTV", "List global parameter values"},  
{ "PLISTA", "List all global parameters"},  
{ "PLISTAV", "List all global parameter values"},
```

### Hand debugging commands:

```
{ "MDRO",   "Motor Debug Rotate Open"},  
{ "MDRC",   "Motor Debug Rotate Close"},  
{ "MDADD",  "Motor Debug Address"},  
{ "MDDAT",  "Motor Debug Data"},
```

### Finger Parameters (use FGET, FSET):

```
{ "S",      "Current motor state"},  
{ "P",      "Current motor position"},  
{ "SG",     "Current strain gauge reading"},  
{ "MOV",    "Maximum open velocity"},  
{ "MCV",    "Maximum close velocity"},  
{ "MSG",    "Maximum allowable finger strain"},  
{ "HSG",    "Highest allowable finger strain"},  
{ "LSG",    "Lowest allowable finger strain"},  
{ "DS",     "Default step size for IO/IC"},  
{ "DP",     "Default position for M"},  
{ "OD",     "Odometer: total motor counts divided by 1000"},  
{ "BDAT",   "Breakaway detection acceleration threshold"},  
{ "BD",     "Flag: breakaway detected during last motion"},  
{ "BP",     "Position of last detected breakaway"},  
{ "BS",     "Flag: motor should stop if breakaway detected"},  
{ "IVEL",   "Initialization Velocity"},  
{ "IOFF",   "Initialization Offset"},  
{ "IHIT",   "Initialization stop hit count"},  
{ "OT",     "Open Target position"},  
{ "CT",     "Close Target position"},  
{ "ACCEL",  "Acceleration"},  
{ "MPE",    "Max dist from desired pos before error"},  
{ "TSTOP",  "Time in ms before motor considered stopped"},  
{ "HOLD",   "Flag: motor should hold position"},  
{ "SGFLIP", "Flag: strain gauge value reversed"},  
{ "EN",     "Flag: motor is by default selected"},
```

### Hand Parameters (use PGET, PSET):

```
{ "TEMP",   "Temperature, in tenths of a degree C"},  
{ "PTEMP",  "Peak temperature, in tenths of a degree C"},  
{ "OTEMP",  "Overtemp temperature, in tenths of a degree C (0 = no max)"},  
{ "UPSECS", "Total powered-up time, in seconds"},  
{ "SN",     "Serial number"},  
{ "BAUD",   "Baud rate divided by 100"},  
{ "CCEE",   "Enable status code feedback upon receiving ^C from host"},  
{ "LOCK",   "Combination lock to set secure variables"},
```

### Low-level motor control parameters (use FGET, FSET):

```
{ "FPG",    "Proportional gain for motor filter"},  
{ "FDZ",    "Derivative zero for motor filter"},  
{ "FTP",    "Torque-mode proportional gain for motor filter"},  
{ "FIP",    "Integral pole for motor filter"},  
{ "SAMPLE", "Sample time register value for HCTL-1100"},
```

### Realtime Loop Parameters (configure LOOP control and feedback blocks):

```
{ "LCV",    "Flag: loop control block contains velocity"},  
{ "LCVC",   "LCV is multiplied by this to get control velocity"},  
{ "LCPG",   "Flag: loop control block contains proportional gain"},  
{ "LFV",    "Flag: loop feedback block contains velocity"},  
{ "LFVC",   "Velocity is divided by this to get LFV"},  
{ "LFS",    "Flag: loop feedback block contains strain"},  
{ "LFAP",   "Flag: loop feedback block contains absolute position"},  
{ "LFDP",   "Flag: loop feedback block contains delta position"},  
{ "LFDPC",  "Delta position is divided by this to get LFDP"},  
{ "LFT",    "Flag: loop feedback block contains temperature"},  
{ "LFDPD",  "Flag: loop feedback delta pos overflow discarded"},
```

```
Error Codes (Errors are additive, ERR 5 =
  No motor board found + Motor not initialized):
{ 0,          "No error",
{ 1,          "No motor board found",
{ 2,          "No motor found",
{ 4,          "Motor not initialized",
{ 16,         "Couldn't reach position",
{ 32,         "Unknown command",
{ 64,         "Unknown parameter name",
{ 128,        "Bad value",
{ 256,        "Tried to write read-only parameter",
{ 1024,       "Too many arguments for this command",
{ 2048,       "Bad loop control block header",
{ 4096,       "Command cannot have motor prefix",
{ 8192,       "Overtemperature",
{ 16384,      "^C sent from host (see CCEE parameter)"},
```